

FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D

00000727 072004




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 4A




FIG. 4B




FIG. 4c




FIG. 4D




FIG. 4E




FIG. 4F














FIG. 4G





1214 7 CRYSTALLIZING

FIG. 7B

LASER ANNEALING

L1215

FIG. 9c

1216 7 THINNING

FIG. 7D




FIG. 8A

LASER ANNEALING




FIG. 8B

THINNING




FIG. 8c

FURNACE ANNEALING











FIG. 8D

00000727 072004






FIG. 10A




FIG. 10B




FIG. 11A




FIG. 11B




FIG. 11C


[illegible]

FIG. 12A




FIG. 12B










FIG. 12c






FIG. 14A




FIG. 14B




FIG. 14C




FIG. 14D




FIG. 15A




FIG. 15B




FIG. 15C

